

Software Release Notification

ISSPA Version 2.1.8 Release

[illegible]

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
NEW FEATURES.....	3
BUG FIXES.....	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUES IN THIS RELEASE.....	3

Introduction

Release 2.1.8 is a maintenance firmware release for the ISSPA.

When upgrading or downgrading to a different version, please follow the method below:

-
- 1) Upload the firmware via FTP
 - 2) Reboot the ISSPA

New Features

1. Attenuator offset values have been added to the redundant web page, and to the SNMP interface.
2. Optional external mute and RF inhibit signals were added to the discrete control port.
3. Added redundant switch position indicators to the web page, and SNMP interface.

Bug Fixes

N/A

Compatible SNMP MIBS

MIB Name	Filename	Date
ISSPA CEFD Root MIB	FW-10874-2-.mib	12/19/2014
ISSPA MIB	FW-0000139B.mib	12/19/2014
ISSPA Traps MIB	FW-0000140-.mib	12/19/2014

Known Issues In This Release

None.