

45xxA Version 1.3.7 Release

Rev #	Description	Date
-	Initial Release version 1.1.1	01/24/2011
A	Release 1.2.1	05/10/2011
B	Release 1.2.2	09/29/2011
C	Release 1.2.3	11/23/2011
D	Release 1.2.4	12/21/2011
E	Release 1.2.5	03/15/2012
G	Release 1.3.1	07/03/2012
H	Release 1.3.2	12/13/2012
J	Release 1.3.3	07/22/2014
K	Release 1.3.4	03/06/2015
M	Release 1.3.5	07/19/2016
N	Release 1.3.6	09/22/2020
P	Release 1.3.7	12/5/2022

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

Release 1.3.7 is a maintenance release for the UT-45xxA, DT-45xxA, and addresses one issue.

Features

N/A

Issues Addressed In This Release

- Hitting clear button on front panel while in Config Menu was changing attenuation setting.

Compatible SNMP MIBs

MIB Name	Filename	Date
45xxA MIB	FW-0000205B_MIB_1_3_1.mib	11-05-2012
45xxA Traps MIB	FW-0000206-_TRAP_1_1_1.mib	01-27-2011

Known Issue(s) In This Release

None

Software Release Notification

Previous Releases

Release 1.1.1

1. Initial release

Release 1.2.1

1. Added Webpage support.
2. Added 1:12 redundancy support.
3. Added 1kHz step size support.

Release 1.2.2

1. Fixed AGC on wide bandwidth (greater than 900Mhz) models.

Release 1.2.3

1. Fixed frequency data sent/received in redundancy for 1kHz step size units.

Release 1.2.5

1. Fixed RMS, RAS, RCS, RAS2, MUT, AID, TSA commands to match legacy 45xx
2. Fixed PACRCS when unit is a backup unit.
3. Updated FPGA

Release 1.3.1

1. Added SNTP and SNMP support.
2. Added TPS and TPE commands.

Release 1.3.2

1. Added dual IF support. Added IFF command.
2. Fixed Non Volatile RAM problem.
3. Fixed Date, CMM, cursor on non-dual IF unit.

Release 1.3.3

1. Fixed redundancy problem.
2. Updated libraries (MQX and SNMP).

Release 1.3.4

1. Fixed redundancy problem and refined the redundancy behavior.

Release 1.3.5

1. Front Panel: Config menu; Output sub-menu; changing values (e.g. Frequency, Attenuator, Rx/Tx On/Off), does not take the user to the Config menu. Further, the changing the

Frequency field results in Rx/Tx: On -> Off and the cursor moves to this field. Changing the Attenuator field updates the Attenuator and moves the cursor to beginning of the Attenuator field. Pressing the “Clear” button returns the user to the Config menu.

Release 1.3.6

1. Fixed the issue on the front panel while in config menu, hitting the clear button was changing the attenuator value to the previously set value.