

# CDM-425 Modem 1.1.3 Release

Applicability
Bulk release 1.1.3 (FW-0021099A_CDM-425_1.1.3) for the CDM-425 Modem. Includes bulk firmware, SNMP MIBs and IQmon.exe.

[illegible]

FSCM No. 4J515

## Table of Contents

<b>THIS RELEASE .....</b>	<b>3</b>
<b>COMPATIBLE BULK VERSIONS .....</b>	<b>3</b>
<b>COMPATIBLE SNMP MIBS .....</b>	<b>3</b>
<b>CHANGE HISTORY .....</b>	<b>3</b>
<b>KNOWN ISSUES .....</b>	<b>4</b>

## This Release

This CDM-425 Modem release has the following changes.

### 1.1.3 Features

- None

### 1.1.3 Fixes

- Fixed V2-ACM in some symbol rates (e.g. 3130.986 ksps) spitting errors or sync loss using internal BERT.
- Fixed RSL monitor function at the rear panel.

## Compatible Bulk Versions

CDM-425 Modem Bulk	CDM-425 Packet Processor Bulk
FW-0021099- (v1.1.1)	FW-0021125- or FW- 0021126- (v1.1.1)
FW-0021099A (v1.1.3)	FW-0021125- or FW- 0021126- (v1.1.1)

## Compatible SNMP MIBS

MIB Name	Filename	Date (mm/dd/yyyy)
<b>CEFD Root MIB</b>	FW10874-2-.mib	08/20/2004
<b>CDM-425 MIB</b>	FW-0021103-.mib	10/02/2017
<b>CDM-425 Traps MIB</b>	FW-0021104-.mib	04/26/2017
<b>DistantEndCDM-425 MIB</b>	FW-0021105-.mib	10/02/2017
<b>CSAT-5060 Transceiver MIB</b>	FW10874-8A.mib	07/09/2013
<b>KST-2000A/B Transceiver MIB</b>	FW10874-9-.mib	11/04/2005

## Change History

This section shows the change history over previous versions.

- None

## **Known Issues**

- PTP is not supported on modems with initial Revision (Revision 2.x) of the hardware.  
PTP is supported for Hardware Revision 3.x or higher.