



Software Release Notification

ISSPA Version 2.2.1 Release

Rev #	Description	Date
-	Initial Release version 2.1.2	02/24/2009
A	Release 2.1.3	08/31/2010
B	Release 2.1.4	10/15/2010
C	Release 2.1.5	11/19/2010
D	Release 2.1.6	12/11/2012
E	Release 2.1.7	02/06/2014
F	Release 2.1.8	12/19/2014
G	Release 2.1.9	8/10/2015
H	Release 2.2.1	10/14/2015

FSCM No. 4J515

Table of Contents

THIS RELEASE	3
COMPATIBLE SNMP MIBS	3
CHANGE HISTORY.....	4
KNOWN ISSUES IN THIS RELEASE.....	4

This Release

Release 2.2.1 is a maintenance firmware release for the ISSPA.

2.2.1 Fixes

- Fix “MUT=2” after power cycle bug.

Compatible SNMP MIBS

MIB Name	Filename	Date
ISSPA CEFD Root MIB	FW-10874-2-.mib	12/19/2014
ISSPA MIB	FW-0000139B.mib	8/10/2015
ISSPA Traps MIB	FW-0000140-.mib	12/19/2014

Change History

This section shows the change history over previous versions.

2.1.9 Features

- Add remote commands for RF Inhibit and External Mute Polarity.
- SNMP “Get” works in any LRS mode.

2.1.9 Fixes

- None.

2.1.8 Features

- Attenuator offset values have been added to the redundant web page, and to the SNMP interface.
- Optional external mute and RF inhibit signals were added to the discrete control port.
- Added redundant switch position indicators to the web page, and SNMP interface

2.1.8 Fixes

- None.

Known Issues In This Release

None.