

## ISSPA 2.2.2 Release Notes

Approval Signatures			
ISSPA Product Manager:	Date:	ISSPA Originator:	Date:

Applicability
Bulk release 2.2.2 (FW-0000086H) for the ISSPA. Includes Bulk firmware and SNMP MIBs.

Rev #	Description	Date (mm/dd/yyyy)
C	Ver 2.1.5, fixed fan fault on power up	11/29/2010
D	Ver 2.1.6 added support for CPA-175	12/11/2012
E	Ver 2.1.7 added SNTP support	02/11/2014
F	Ver 2.1.8 added Inhibit, Ext Mute, Redundant & offset webpage, SNMP	12/19/2014
G	Ver 2.1.9 added remote cmds for RF Inhibit, ext mute polarity, SNMP get works in any LRS mode	08/16/2015
H	Ver 2.2.1 fix "MUT=2" after power cycle bug	11/03/2015
J	Ver 2.2.2 fix random forward power drop	08/09/2019

FSCM No. 4J515

## Table of Contents

<b>THIS RELEASE .....</b>	<b>3</b>
<b>COMPATIBLE SNMP MIBS .....</b>	<b>3</b>
<b>CHANGE HISTORY .....</b>	<b>3</b>
<b>KNOWN ISSUES .....</b>	<b>3</b>

## This Release

This is the revision J release of ISSPA Firmware.

### 2.2.2 Fix

- Random Forward Power drop

## Compatible SNMP MIBS

MIB Name	Filename	Date (mm/dd/yyyy)
<b>ISSPA Traps MIB</b>	FW-00000140-_rev111.mib	03/04/2009
<b>ISSPA MIB</b>	FW-00000139B_rev113.mib	08/16/2015
<b>CEFD Root MIB</b>	FW10874-2-.mib	08/20/2004

## Change History

### Rev 2.1.5: Fixed

- fixed fan fault on power up

### Rev 2.1.6 Features

- added support for CPA-175.

### Rev 2.1.7 Features

- added SNTP support

### Rev 2.1.8 Features

- added Inhibit, Ext Mute, Redundant & offset on webpage,
- SNMP added SNMP

### Rev2.1.9 Features

- added remote cmds for RF Inhibit, ext mute polarity,
- SNMP get works in any LRS mode.

### Rev2.2.1 Fix

- fix "MUT=2" after power cycle bug

## Known Issues

None