

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE.....	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

Release 1.1.3 is a maintenance release for the LGaN 50W Ku.

Features

- N/A.

Issues Addressed In This Release

- Adjusted tolerance for RF24V monitor.
- Changed recovery IP address to 169.254.233.175.

Note: unit should be software upgraded, power cycle, when full initialized, power cycle again.

Compatible SNMP MIBs

MIB Name	Filename	Date
Root MIB	FW10874-2.mib	Per PLM
LGaN MIB	FW-0021149A_v112.mib	Per PLM
LGaN Traps MIB	FW-0021148-_v111.mib	Per PLM

Known Issue(s) In This Release

- N/A

Software Release Notification

Previous Releases

Release 1.1.1

1. Initial release

Release 1.1.2

1. Fix FSK.

Release 1.1.3

1. Adjusted tolerance for RF24V monitor.
2. Change recovery IP address to 169.254.233.175