

CDM-Qx Version 1.6.10 Release

Applicability

Firmware upgrade (FW/11245) for any previous release of CDM-Qx units. Includes bulk firmware and SNMP MIBs.

| Rev # | Description | Date |
|-------|--------------------------------|------------|
| - | Initial Release, version 1.1.1 | 3/21/2005 |
| A | Release of version 1.1.2 | 4/21/2005 |
| B | Release of version 1.1.3 | 5/25/2005 |
| C | Release of version 1.1.4 | 8/02/2005 |
| D | Release of version 1.1.5 | 9/12/2005 |
| E | Release of version 1.1.6 | 11/22/2005 |
| F | Release of version 1.2.1 | 02/27/2006 |
| G | Release of version 1.2.2 | 05/05/06 |
| H | Release of version 1.3.1 | 07/31/06 |
| J | Release of version 1.3.2 | 10/05/06 |
| K | Release of version 1.4.1 | 11/14/06 |
| L | Release of version 1.4.2 | 02/15/07 |
| M | Release of version 1.4.3 | 06/05/07 |
| N | Release of version 1.5.1 | 06/26/07 |
| P | Release of version 1.5.2 | 11/14/07 |
| R | Release of version 1.6.1 | 01/28/08 |
| T | Release of version 1.6.2 | 05/09/08 |
| U | Release of version 1.6.3 | 06/15/08 |
| V | Release of version 1.6.4 | 03/17/09 |
| W | Release of version 1.6.5 | 04/08/09 |
| Y | Release of version 1.6.6 | 05/20/09 |
| AA | Release of version 1.6.7 | 08/25/11 |
| AB | Release of version 1.6.8 | 10/18/11 |
| AC | Release of version 1.6.9 | 02/17/12 |
| AD | Release of version 1.6.10 | 09/10/12 |

FSCM No. 4J515

Table of Contents

| | |
|--|----------|
| INTRODUCTION..... | 3 |
| FEATURES..... | 3 |
| ISSUES ADDRESSED IN THIS RELEASE | 3 |
| ADDRESSES AN ISSUE WHERE THE MODULATOR RTS SIGNAL , DEMODULATOR RTS SIGNAL, AND THE DEMODULATOR EXTERNAL CARRIER MUTE SIGNAL WERE NOT TURNING THE TRANSMIT CARRIER ON AND OFF.... | 3 |
| COMPATIBLE SNMP MIBS | 3 |
| KNOWN ISSUE(S) IN THIS RELEASE | 3 |

Introduction

This is a release of firmware for the CDM-Qx.

Features

None

Issues Addressed In This Release

Addresses an issue where the Modulator RTS Signal , Demodulator RTS Signal, and the Demodulator External Carrier Mute Signal were not turning the Transmit Carrier ON and OFF.

Addresses an issue where An EDMAC Slave (DNI++) improperly programs the Modem when Remote Commands TDR and RDR are executed.

Compatible SNMP MIBs

| MIB Name | Filename | Date |
|------------------|----------------|------------|
| CDM-Qx CEFD Root | FW10874-2-.mib | 07/27/2005 |
| CDM-Qx MIB | FW11247-1A.mib | 06/30/2006 |
| CDM-QxL MIB | FW11247-3-.mib | 03/08/2006 |
| CDM-Qx Traps | FW11247-2-.mib | 08/17/2005 |

Known Issue(s) In This Release