

CRS-300 Switch, version 2.18 Release

Approval Signatures			
Product Manager:	Dennis Bennett	Originator:	Mike McEwin

Applicability
Complete firmware release/upgrade for any/all previous release of CRS-300 Switch System operating with CDM-700 modems. FW/12520

Revision History			
Rev #	Description	Date	Prepared by
-	Initial Release, version 2.01	8/1/2006	A. Miller
A	Version 2.03	10/2/2006	A. Miller
B	Version 2.12	4/16/2007	A. Miller
C	Version 2.16	4/21/2008	M. McEwin
D	Version 2.17	7/01/2008	M. McEwin
E	Version 2.18	9/21/2009	M. McEwin

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

This is a release of firmware for the CRS-300 Switch system for operation with CDM-700 modems.

Features

No additional features were added.

Issues Addressed In This Release

- Switch could lock up remote comm. port requiring power cycle to fix.
- Switch would exhibit comm. losses to modems while modems were being polled directly via SNMP.
- Switch will now place redundant modem online with a TX fault if the traffic modem it is bridging has all three (RX, TX, and Unit) faults.

Known Issue(s) In This Release

None.