



CDM-700/700L Modem

Release 1.3.3

Software Release Notification

CDM-700/700L Modem 1.3.3 Release

Approval Signatures			
Product Manager: Ray Swinney	Date: 05/10/2010	Originator: Mike McEwin	Date: 05/10/2010

Applicability
Bulk release 1.3.3 (FW10236P) for CDM-700 and CDM-700L Base Modem. Includes bulk firmware and SNMP MIBs.

Revision History			
Rev #	Description	Date	Prepared by
-	Initial Release, version 1.1.1	3/02/2006	Christian Tabora
A	Release of version 1.1.2	3/23/2006	Jerome Brown
B	Release of version 1.1.3	4/04/2006	Christian Tabora
C	Release of version 1.1.4	6/28/2006	Jerome Brown
D	Release of version 1.1.5	8/01/2006	Jerome Brown
E	Release of version 1.1.6	9/29/2006	Jerome Brown
F	Release of version 1.1.7	10/18/2006	Jerome Brown
G	Release of version 1.1.8	1/8/2007	Jerome Brown
G1	Release of version 1.1.8	2/8/2007	Jeff Harig
H	Release of version 1.2.1	2/16/2007	Jerome Brown
	Ammendum to Release Notes	5/22/2007	Jerome Brown
J	Release of version 1.2.2	6/26/2007	Jerome Brown
K	Release of version 1.2.3	11/16/2007	Jerome Brown
L	Release of version 1.3.0	4/24/2007	Jerome Brown
M	Release of version 1.3.1	12/9/08	Jerome Brown
N	Release of version 1.3.2	8/27/09	Nick Myers
P	Release of version 1.3.3	05/10/2010	Mike McEwin

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
FEATURES ADDED	3
ISSUES ADDRESSED.....	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUES	3

Introduction

This is a release of firmware for CDM-700 and CDM-700L modems.

Features Added

None.

Issues Addressed

1. 1:1 redundancy using 64QAM modulation type could result in an incorrect carrier loop gain.
2. A Receive AIS fault would reprogram the G.703 interface.

Compatible SNMP MIBS

MIB Name	Filename	Release Date
CDM-700 CEFD Root MIB	FW10874-2-.mib	4/19/2004
CDM-700 MIB	FW10236-4E.mib	12/09/2008
CDM-700 Traps MIB	FW12635-1A.mib	4/24/2008

Known Issues

None.