

## CDM-600L Modem, version 1.5.6 Release

Approval Signatures	
Product Manager: Ray Swinney	Originator: Mike McEwin

Applicability
Complete firmware upgrade for any/all previous releases of CDM-600L Modems, F1451

		Revision History			
Rev	Description	M&C	FPGA	Date	Prepared by
-	Initial Release, Version 1.1.1	10BE	8B06	5/19/03	H. Nguyen
A	Release of version 1.1.2	5255	8B06	8/18/03	A. Miller
B	Release of version 1.1.3	286C	7646	10/7/03	A. Miller
C	Release of version 1.1.4	E8AB	7646	10/13/03	A. Miller
D	Release of version 1.1.5	A8A0	7646	12/10/03	A. Miller
E	Release of version 1.1.6	5F53	7646	4/14/04	A. Miller
F	Release of version 1.2.0	9B04	9E31	6/22/04	A. Miller
G	Release of version 1.2.1	BE34	8E2D	9/9/04	A. Miller
H	Release of version 1.2.2	A738	8E2D	1/10/05	A. Miller
J	Release of version 1.3.0	3D76	C571	3/21/05	A. Miller
K	Release of version 1.3.1	B847	BEF6	5/19/05	A. Miller
L	Release of version 1.4.0	34C3	C8EE	10/20/05	A. Miller
M	Release of version 1.4.1	7785	8CCD	1/10/06	A. Miller
N	Release of version 1.4.3	6F21	D1BE	1/11/07	A. Miller
P	Release of version 1.4.4	E435	D1BE	1/26/07	A. Miller
R	Release of version 1.4.5	3F68	D1BE	9/17/07	A. Miller
T	Release of version 1.4.6 - unavailable	693C	D1BE	11/13/07	A. Miller
U	Release of version 1.4.7	6925	D1BE	12/4/07	A. Miller
V	Release of version 1.4.8	848B	D1BE	3/04/08	M. McEwin
W	Release of version 1.4.9	2A5A	D1BE	5/28/08	M. McEwin
Y	Release of version 1.5.0	2D1D	D1BE	7/09/08	M. McEwin
AA	Release of version 1.5.1	7625	7C8E	6/03/09	M. McEwin
AB	Release of version 1.5.2	2881	7C8E	11/02/09	M. McEwin
AC	Release of version 1.5.3	98F1	EAE9	03/08/2010	M. McEwin
AD	Release of version 1.5.4	E5D0	EAE9	04/13/2010	M. McEwin
AE	Release of version 1.5.5	EFE8	EAE9	05/19/2010	M. McEwin
AF	Release of version 1.5.6	EFA6	EAE9	01/19/2010	M. McEwin

## Table of Contents

<b>INTRODUCTION.....</b>	<b>3</b>
<b>NEW FEATURES.....</b>	<b>3</b>
<b>ISSUES ADDRESSED IN THIS RELEASE .....</b>	<b>3</b>
<b>KNOWN ISSUE(S) IN THIS RELEASE .....</b>	<b>3</b>

## **Introduction**

This is a release of firmware for the CDM-600L modem.

## **New Features**

None.

## **Issues Addressed In This Release**

1. Fixed issue when TX clock source is changed from looptiming to internal clock using remote command TCK=2 to TCK=0 the timing of ST doubles.

## **Known Issue(s) In This Release**

None.