
SE-FW5804

Rev. A

F05804 Software Family

Used on the SkyWire™ MDX420
Satellite Network Gateway

Introduction

This software errata sheet provides updated information on the embedded SkyWire™ MDX420 software package

This document addresses known issues with the software package as released, potential side effects, and methods to work around the issues.

Table 1 describes the issues the affected software and the expected corrected software.

Table 1 - SkyWire Product Issue

SkyWire – Software / Firmware package		
Issue	Affected version	Corrected Version
Revision K is not backward compatible with earlier revisions.	F05804 – K	No correction required .

Problem Description

Due to added communications features and the ability to rapidly invite sites into the network over a variety of entry modes, Revision K of the SkyWire™ firmware is not backward compatible with previous revisions.

Operational Side effects

You can not have a network where some Gateways are running Revision J or earlier and other sites are running Revision K. All of the SkyWire™ Gateways must be updated to Revision K.

Work around

There is no work around.