



**SLM-9000C Modem**  
**Release 1.1.1**

**Software Release Notification**

**SLM--9000C Modem 1.1.1 Release**

Approval Signatures			
SLM-9000C Product Manager: Carey Dietz	Date:	SLM-9000C Originator: Carey Dietz	Date:

Applicability
Bulk release 1.1.1 (FW-0000401-) for the SLM-9000C Modems. Includes bulk firmware and SNMP MIBs.

Revision History			
Rev #	Description	Date	Prepared by
-	Initial Release, version 1.1.1	07/07/2011	Carey Dietz

FSCM No. 4J515

## Table of Contents

<b>INTRODUCTION.....</b>	<b>3</b>
<b>FEATURES.....</b>	<b>3</b>
<b>DEFECT FIXES .....</b>	<b>3</b>
<b>COMPATIBLE SNMP MIBS .....</b>	<b>3</b>
<b>FIRMWARE COMPATIBILITY.....</b>	<b>3</b>
<b>KNOWN ISSUE(S) IN THIS RELEASE .....</b>	<b>3</b>

## Introduction

This is the Initial Release of the SLM-9000C Modem FW-0000401- Version 1.1.1

## Features

- Initial Release.

## Defect Fixes

- Initial Release.

## Compatible SNMP MIBS

MIB Name	Filename	Date
<b>CEFD Root MIB</b>	FW10874-2-.mib	8/20/2004
<b>SLM-9000C MIB</b>	FW-0000365A.mib	6/03/2010
<b>SLM-9000C Traps</b>	FW-0000366-.mib	2/01/2010

## Firmware Compatibility

Since the SLM-9000C Modem does not contain any option cards with unique firmware at this time, there are no compatibility issues to report.

## Known Issue(s) In This Release

- SNMP SETs for both Tx and Rx frequency will wrongly accept a frequency with a 1 Hz step size and round it to the appropriate 100 Hz step.