

CPA/KPA/XPA Version 1.1.8 Release

Approval Signatures			
Product Manager:	Date:	Originator:	Date:
Brad Thillmony		Lazaro Cajegas III	

Applicability
Firmware upgrade (FW/12036) for any previous release of outdoor SSPA model CPA/KPA/XPA-xxx-yyyy series (where: xxx=RF power, yyyy=frequency range).

Revision History			
Rev #	Description	Date	Prepared by
-	Initial Release, version 1.1.1	8/16/2005	Lazaro Cajegas III
A	Release version 1.1.2	5/23/2006	Nick Myers
B	Release version 1.1.3	6/28/2006	Nick Myers
C	Release version 1.1.4	9/5/2006	Nick Myers
D	Release version 1.1.5	9/26/2006	Nick Myers
E	Release version 1.1.6	12/07/2006	Carey Dietz
F	Release version 1.1.7	12/14/2006	Carey Dietz
G	Release version 1.1.8	1/26/07	Carey Dietz

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

The low-power outdoor SSPA firmware release 1.1.8 includes a single bug fix.

Features

1. None

Issues Addressed In This Release

1. Fixed a problem with RF Power monitoring accuracy below 0 degrees C.

Known Issue(s) In This Release

1. None.