

Software Release Notification

CRS-300 Switch, version 1.40 Release

Approval Signatures			
Product Manager:	Jeff Harig	Originator:	Anne Miller

Applicability
Complete firmware upgrade for any/all previous releases of CRS-300 Switch Systems, Fwc1435

Rev	Description	Checksums:			Revision History	
		Bulk	M&C	FPGA	Date	Prepared by
A	Initial Release, version 1.01	8894	626A	262A	4/30/2002	A. Miller
B	Release of version 1.02	AE75	5C6F	5206	6/20/2002	A. Miller
C	Release of version 1.03	AFD7	5DD1	5206	7/31/2002	A. Miller
D	Release of version 1.06	92B7	E4BD	5206	8/7/2002	A. Miller
E	Release of version 1.07	9BFC	49F6	5206	9/11/2002	A. Miller
F	Release of version 1.08	9BFD	49F7	5206	10/28/2002	A. Miller
G	Release of version 1.09	9C06	4A00	5206	11/08/2002	A. Miller
H	Release of version 1.10	1C02	C9FC	5206	11/18/2002	A. Miller
J	Release of version 1.11	18A8	C6A2	5206	2/2/04	A. Miller
K	Release of version 1.12	2875	D66F	5206	6/23/04	A. Miller
L	Release of version 1.13	228E	D088	5206	10/21/04	A. Miller
M	Release of version 1.20	5A6E	0868	5206	11/11/04	A. Miller
N	Release of version 1.30	007B	AE75	5206	5/19/05	A. Miller
P	Release of version 1.31	CFD0	7DCA	5206	5/31/05	A. Miller
R	Release of version 1.32	624F	1049	5206	8/22/05	A. Miller
T	Release of version 1.33	624C	1046	5206	9/27/05	A. Miller
U	Release of version 1.34	E070	8E6A	5206	10/24/05	A. Miller
V	Release of version 1.35	FD2F	0C38	F027	2/27/06	A. Miller
W	Release of version 1.40	0D59	3078	DCE1	6/14/06	A. Miller

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
NEW FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

The main purpose of this latest release of CRS-300 firmware, version 1.40, is to add support for new Traffic Modem Interfaces (TMIs) and Redundant Modem Interfaces (RMIs). This version adds complete support for the SLM-5650 modem. Note: there are important cabling changes. Please refer to the updated CRS-300 manual.

New Features

- Capability was added for new TMIs and RMIs.
- This version provides complete support for the SLM-5650 modem. Note: there are important cabling changes. Please refer to the updated CRS-300 manual.

Issues Addressed In This Release

- Alarm relay issue fixed, refer to the latest copy of the manual for explanation.

Known Issue(s) In This Release

None known.