



F05804-D Software Family

Used on SkyWire MDX420 Satellite Network Gateway

Errata Sheet

July 17, 2008

Introduction

This errata sheet provides updated information on the embedded SkyWire MDX420 software package

This document addresses known issues with the software package as released, potential side effects, and methods to work around the issues.

Table 1 describes the issues the affected software and the expected corrected software.

Table 1 - SkyWire Product Issue

SkyWire – Software / Firmware package		
Issue	Affected version	Corrected Version
Revision D is not backward compatible with earlier revisions	F05804 - D	No correction required

Problem Description

Due to added security features and the ability to upgrade firmware over the air, Revision D of the SkyWire firmware is not backward compatible with previous revisions. Going forward, newer revisions are expected to be backward compatible to Revision D.

Operational Side effects

You can not have a network where some Gateways are running Revision C or earlier and other are running Revision D. All of the SkyWire Gateways must be updated to Revision D or later.

Work around

There is no work around.