

## PCB-4X00A Ethernet Phase Combiner 1.1.6 Release

Approval Signatures			
PCB-4X00A Product Manager:	Date:	PCB-4X00A Originator:	Date:

Applicability
Bulk release 1.1.6 (FW-0021045E) for the PCB-4X00A (PCB-4000A 1+1 and PCB-4300A 1:2) Ethernet Phase Combiner. Includes Bulk firmware and SNMP MIBs.

Rev #	Description	Date (mm/dd/yyyy)
-	Initial Release, version 1.1.1	04/24/2017
A	Version 1.1.2 added SNMP trap support	11/09/2017
B	Fixed virtual commands problem	12/27/2017
C	Added Sntp support	01/16/2018
D	Fixed Mute in a single HPOD configuration.	03/05/2018
E	Fixed Gateway Address not saving.	09/26/2019

FSCM No. 4J515

## Table of Contents

<b>THIS RELEASE .....</b>	<b>3</b>
<b>COMPATIBLE SNMP MIBS .....</b>	<b>3</b>
<b>CHANGE HISTORY .....</b>	<b>3</b>
<b>KNOWN ISSUES .....</b>	<b>3</b>

## This Release

Fixed Gateway Address not being saved.

## Compatible SNMP MIBS

MIB Name	Filename	Date (mm/dd/yyyy)
PCB-4X00A MIB	FW-0021047C_v113.mib	01/16/2018
CEFD Root MIB	FW10874-2-.mib	08/20/2004
PCB-4X00A MIB Traps	FW-0021048-_v111.mib	11/09/2017

## Change History

None

## Known Issues

None

## Previous Releases

### **Release 1.1.1**

- Support monitor and control of Phase Combiner system through SNMP user interface.

### **Release 1.1.2**

- Added support for SNMP Traps.

### **Release 1.1.3**

- Fixes an infrequent problem with HPOD commands (virtual commands). This firmware applies to both PCB-4000A 1+1 Phase Combiner and PCB-4300A 1:2 Phase Combiner.

### **Release 1.1.4**

- Added support for SNTP.

### **Release 1.1.5**

- Fixed Mute problem for single HPOD configuration(i.e. The Mute was toggling).