

LGaN 100W Ku Version 1.1.6 Release

Rev #	Description	Date
E	Release version 1.1.6	Per PLM
D	Release version 1.1.5	Per PLM
C	Release version 1.1.4	Per PLM
B	Release version 1.1.3	Per PLM
A	Release version 1.1.2	Per PLM
-	Initial Release version 1.1.1	Per PLM

FSCM No. 4J515

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

Release 1.1.5 is a maintenance release for the 100W Ku-Band LGaN.

Features

none

Issues Addressed In This Release

- Fixed Attenuator Initialization.
- Fixed External Reference Flag & 5Mhz/10Mhz Flag.

Compatible SNMP MIBs

MIB Name	Filename	Date
Root MIB	FW10874-2.mib	Per PLM
LGaN MIB	FW-0021149B_v113.mib	Per PLM
LGaN Traps MIB	FW-0021148A_v112.mib	Per PLM

Known Issue(s) In This Release

- N/A