

Table of Contents

INTRODUCTION.....	3
FEATURES.....	3
ISSUES ADDRESSED IN THIS RELEASE.....	3
COMPATIBLE SNMP MIBS	3
KNOWN ISSUE(S) IN THIS RELEASE	3

Introduction

Release 1.1.4 is a maintenance release for the RC-1170/1270.

Features

Maintenance release for RC-1170/1270 Redundant Controller. This firmware supports 1:2 and 1:1 LNA/LNB redundancy system.

Issues Addressed In This Release

- Added support for Priority setting in 1:2 configuration. See manual for specific details.
- In 1:2 configuration, if in auto mode and no faults on all three units, unit 2 will default to the offline unit.

Compatible SNMP MIBs

MIB Name	Filename	Date
CEFD Root MIB	FW-10874-2-.mib	11-12-2014
RED MIB	FW-0021341B.mib	12-21-2022
RED Traps MIB	FW-0021342A.mib	5-3-2022

Known Issue(s) In This Release

None

Software Release Notification

Previous Releases

Release 1.1.1

1. Initial release

Release 1.1.2

1. Fix switch logic issue with 1:1 redundancy switch.
2. Update mask logic for PS1 Input Detect/PS2 Input Detect.

Release 1.1.3

1. Add Mask setting.
2. Fix webpage when not in ethernet mode.
3. Fix issue with mac address display with firefox browser.

Release 1.1.4

1. Add Priority setting.
2. Make Unit 2 the default offline unit in 1:2 configuration.