



# CDM-570/570L Modem 1.6.19 Release

[illegible]

## Table of Contents

<b>FEATURES.....</b>	<b>3</b>
<b>DEFECT FIXES .....</b>	<b>3</b>
<b>COMPATIBLE SNMP MIBS .....</b>	<b>3</b>
<b>KNOWN ISSUE(S) IN THIS RELEASE .....</b>	<b>3</b>

## INTRODUCTION

The CDM-570/570L Base Modem Release 1.6.19 fixes a SNMP defect.

## Features

- None

## Defect Fixes

- Fixes bug that MIB OID "cdm570RxBERString" didn't work. (TT #11004)
- Removes "cdm570RedundancyAlarm" notification OID from CDM-570 MIB file.

## Compatible SNMP MIBS

MIB Name	Filename	Date
CDM-570 CEFD Root MIB	FW10874-2-.mib	8/20/2004
CDM-570 MIB	FW10874-4L.mib	6/01/2015
CDM-570 v1 Traps	FW10874-5a.mib	1/26/2005
CDM-570L BUC/LNB MIB	FW10874-6B.mib	3/07/2007
CDM-570L BUC/LNB v1 Traps	FW10874-7-.mib	1/26/2005
CSAT-5060 Transceiver MIB	FW10874-8-.mib	11/23/2005
KST-2000A/B Transceiver MIB	FW10874-9-.mib	11/04/2005

## Known Issue(s) In This Release

None.