



DMD1050 - Card Modem

Release AM.1 (4.9.1)

Software Release Notification

DMD1050 Family Card Modem Release AM.1 (4.9.1)

Applicability
Bulk release FW/5775AM (4.8.42)

Revision History		
Rev #	Description	Date
AE	4.1 Improved EbNo monitor display and support Comtech Ethernet Format and PL0000735 baseband card.	02/17/2011
AF	4.2 Delayed check of High Stability Clock.	01/11/12
AG	Skipped version	
AH	Skipped version	
AK	Skipped version	
AL41	Initial Release of DMD1050T (LDPC and TRANSEC)	10/06/2016
AM	4.8.42 Addressed web server lockup issue	Per PLM
AM.1	4.9.1 Corrects malformed bogus pause frames on the Ethernet Interface	Per PLM

INTRODUCTION

This maintenance release package contains; a bug fix.

MnC Alterations

1. Fixes bug Ethernet interface outputs malformed bogus pause frames.

FPGA Alterations

NONE

Known Issue(s) In This Release

1. RSL Monitor could be out of spec at higher frequency range.