

Last Time Buy Notification **CDM-570 (IP), CDD-564, CDD-562**

We are committed to providing our valued customers with cost-effective products that meet the high quality standards demanded by our community. There are occasions when we are no longer able to manufacture products due to various reasons. Our goal is to inform our customers of such issues and provide alternative solutions.

Last Time Buy Reason:

Due to parts shortages and the availability of next generation, more feature-rich products supplied by Comtech EF Data, we are announcing a last time buy for select models of our 500 Series Satellite Modems and Demodulators.

Last Time Buy Deadline:

We are accepting orders for the last time buy products on a first come first serve basis. After this time, we may not be able to guarantee availability of the products. On August 1, 2015, should we have sufficient parts to continue to manufacture these products, we will need to increase the product prices to fulfill any requested orders.

Support:

We will continue to support repairs on End-of-Life (EOL) products as long as component/material obsolescence allows us to do so.

Products Impacted and Best Fit Replacements:

Last Time Buy Product	Best Fit Replacement Product	Best Fit Availability
CDM-570-IP	CDM-570A-IP	Available Now
CDM-570L-IP	CDM-570AL-IP	Available Now
CDM-570-IPEN	CDM570A-IPEN	August 2015*
CDM-570L-IPEN	CDM-570AL-IPEN	August 2015*
CDD-564	CDD-564A	Available Now
CDD-564EN	CDD-564AEN	August 2015*
CDD-564L	CDD-564AL	Available Now
CDD-564LEN	CDD-564ALEN	August 2015*
CDD-562L	CDD-562AL	Available Now
CDD-562LEN	CDD-562ALEN	August 2015*

*Estimated

Compatibility:

Products listed as the best fit replacement products have been engineered to be backwards compatible in the following ways:

- Best fit replacements will have the same or more capability as the last time buy product
- Best fit replacements will have the equivalent or better performance specifications as last time buy product
- Best fit replacements can be used with the same redundancy switches and can be mixed (new and old) within the same redundancy switch
- Best fit replacements will NOT have the exact same MIB files and drivers may need to be edited to accommodate new MIBs

Further Questions:

If you have further questions or require more information, please contact your sales representative.

Best Regards,
Comtech EF Data

2114 West 7th Street, Tempe, Arizona 85281 USA
Voice: +1.480.333.2200 • Fax: +1.480.333.2540 • Email: sales@comtechefdata.com

See all of Comtech EF Data's Patents and Patents Pending at <http://patents.comtechefdata.com>

Comtech EF Data reserves the right to change specifications of products described in this document at any time without notice and without obligation to notify any person of such changes. Information in this document may differ from that published in other Comtech EF Data documents. Refer to the website or contact Customer Service for the latest released product information